

# Journal of Civil Structural Health Monitoring

## Structural and health assessment of historic timber roofs from the Convent of Christ in Tomar --Manuscript Draft--

<b>Manuscript Number:</b>	CSHM-D-19-00067
<b>Full Title:</b>	Structural and health assessment of historic timber roofs from the Convent of Christ in Tomar
<b>Article Type:</b>	Original Paper
<b>Corresponding Author:</b>	Maxime Paul Augustin Verbist, MSc Architectural Civil Engineering Universidade do Minho Escola de Engenharia Guimarães, PORTUGAL
<b>Corresponding Author Secondary Information:</b>	
<b>Corresponding Author's Institution:</b>	Universidade do Minho Escola de Engenharia
<b>Corresponding Author's Secondary Institution:</b>	
<b>First Author:</b>	Maxime Paul Augustin Verbist, MSc Architectural Civil Engineering
<b>First Author Secondary Information:</b>	
<b>Order of Authors:</b>	Maxime Paul Augustin Verbist, MSc Architectural Civil Engineering Filipe T. Matos, MSc Civil Engineering Jorge M. Branco, PhD Civil Engineering
<b>Order of Authors Secondary Information:</b>	
<b>Funding Information:</b>	
<b>Abstract:</b>	<p>Before coming up with any important decision of intervention in the restoration process of existing buildings, the assessment of the conservation state is required as regards heritage timber structures, and especially, for those that suffered a lack of maintenance in their service life. In that context, three timber roof structures from the Convent of Christ in Tomar, Portugal, have been selected and investigated. To this end, a research methodology has been introduced and applied to these case studies into four main steps: (i) Visual inspection; (ii) Non-destructive wood diagnosis; (iii) Structural safety evaluation; (iv) Prevention and intervention measures. For the visual inspection, every element and joint constituting the roof structures have been received scrutiny through stressing the wood species, the different construction stages, and last but not least, their respective geometry. As regards the encountered pathologies, structural disorders (e.g. accidental failure, serviceability defects...) and wood-deteriorations due to biological agents (e.g. wood-destroying fungi or insects) have been reported, which ineluctably leads to a likely decrease of the mechanical performances of the roof structure. In order to estimate the residual element cross-section and elastic modulus, wood diagnosis has been carried out through using three relevant non-destructive tests: (i) Ultrasonic Pulse Velocity; (ii) Drilling Resistance; (iii) Impact penetration. From the collected data, the three timber roof structures have been modelled on a commercial software in order to check their safety and integrity. Based on those outcomes, some prevention and intervention measures have been lastly proposed case by case.</p>

[Click here to view linked References](#)

# 1 Structural and health assessment of historic timber roofs 2 from the Convent of Christ in Tomar

---

3 Maxime Verbist<sup>a,\*</sup>, Filipe T. Matos<sup>a</sup>, Jorge M. Branco<sup>a</sup>

4 <sup>a</sup> *ISISE, University of Minho, Campus de Azurém, 4800-058, Guimarães, Portugal*

5 \* *Corresponding author*

6 *E-mail addresses:* [verbist.maxime@hotmail.com](mailto:verbist.maxime@hotmail.com) (M. Verbist),

7 [filipetmatos@gmail.com](mailto:filipetmatos@gmail.com) (F.T. Matos), [jbranco@civil.uminho.pt](mailto:jbranco@civil.uminho.pt) (J.M. Branco).

---

## 8 **Abstract:**

9 Before coming up with any important decision of intervention in the restoration process of  
10 existing buildings, the assessment of the conservation state is required as regards heritage  
11 timber structures, and especially, for those that suffered a lack of maintenance in their service  
12 life. In that context, three timber roof structures from the Convent of Christ in Tomar,  
13 Portugal, have been selected and investigated. To this end, a research methodology has been  
14 introduced and applied to these case studies into four main steps: (i) Visual inspection; (ii)  
15 Non-destructive wood diagnosis; (iii) Structural safety evaluation; (iv) Prevention and  
16 intervention measures. For the visual inspection, every element and joint constituting the roof  
17 structures have been received scrutiny through stressing the wood species, the different  
18 construction stages, and last but not least, their respective geometry. As regards the  
19 encountered pathologies, structural disorders (e.g. accidental failure, serviceability defects...)  
20 and wood-deteriorations due to biological agents (e.g. wood-destroying fungi or insects) have  
21 been reported, which ineluctably leads to a likely decrease of the mechanical performances of  
22 the roof structure. In order to estimate the residual element cross-section and elastic modulus,  
23 wood diagnosis has been carried out through using three relevant non-destructive tests: (i)  
24 Ultrasonic Pulse Velocity; (ii) Drilling Resistance; (iii) Impact penetration. From the collected  
25 data, the three timber roof structures have been modelled on a commercial software in order  
26 to check their safety and integrity. Based on those outcomes, some prevention and  
27 intervention measures have been lastly proposed case by case.

## 28 **Keywords:**

29 *Timber roof structures; Diagnosis; Pathologies; Non-destructive testing; Modelling*

# 1. Introduction

Nowadays, it is generally agreed that existing buildings of heritage values constitute an integral part of the historic legacy of humanity to be preserved for many further generations to come. With modern societies targeting further the matter of sustainability, the conservation of such buildings appears to be a good alternative from the economic, environmental, social and cultural points of view. Even if this concept only came up in the last decades, a generalized degradation and abandonment state were already reported for the greatest part of the built heritage. Due to lack of maintenance often leading to excessive moisture content exposure, various pathologies of a biological, physical or chemical nature may develop within timber structures, resulting in the reduction of their long-term mechanical performances in their service life [1]. Although structural disorders (e.g. instability, high deformation, accidental failure of elements or joints...) caused by a bad design at the initial construction stage are rarely met, they may still appear as a consequence of a significant loading change, over many intervention periods in the edifice history.

Prior to any decisive intervention in buildings of heritage values, it is crucial to develop a multidisciplinary method that combines several tasks and aspects from different fields of knowledge. As regards the diagnosis and restoration of historic timber structures, many guidelines and methodological approaches can be found from the available literature [2, 3, 4, 5, 6]. Furthermore, two charters from ICOMOS [7, 8] also give some principles for the analysis, conservation and structural restoration of architectural heritage, with a focus on the preservation of historic timber structures. As reference to case studies and state-of-the arts dealing with timber roof structures, it can be stated many works [9, 10, 11, 12, 13, 14, 15, 16] in which are introduced efficient methodologies of inspection and diagnosis completed till reaching the decision of intervention, mostly driven by the conservation with strengthening or repair possibilities.

Wood can be considered as a very important raw material throughout the ages, with a fundamental structural role in historic buildings around the world. In that context, the present work aims at assessing the conservation state of existing timber structures, and finally, at proposing appropriate prevention and intervention means to ensure good maintenance conditions in the near future. To this end, the Convent of Christ in Tomar (Portugal) has been chosen, with the evaluation of three timber roof structures badly preserved over time. Thereby, a methodology of inspection and diagnosis has been proposed and applied to these case studies into four main steps: (i) Visual inspection; (ii) Non-destructive wood diagnosis;

63 (iii) Safety structural evaluation; (iv) Prevention and intervention measures. Before going  
64 ahead with the assessment of timber roof structures, a few words should be said about the  
65 history of the building, namely the Convent of Christ, and the research methodology selected  
66 in the present work.

## 67 **2. Materials and method**

### 68 **2.1. The Building: Convent of Christ**

69 Standing at the top of the hill, the Convent of Christ (Fig. 1) overhang the historic city-centre  
70 of Tomar, in Portugal, as a strong national symbol of “Reconquista Portuguesa”, and  
71 afterwards, of the opening up towards other civilizations through overseas explorations. The  
72 whole historic building is the testimony to an eclectic architecture over a five-hundred-year  
73 period, combining Romanesque, Gothic, Manueline, Renaissance, Mannerist and Baroque  
74 elements. As first traces of the monumental complex, the 12<sup>th</sup> century Tomar Castle was built  
75 by D. Gualdim Pais, for which the Oratory “Charola” and walls surrounding the convent still  
76 remain nowadays. In the 14<sup>th</sup> century, the Order of Christ substituted the Order of Knights  
77 Templar, through progressively restraining the activities of friars to religion only. The next  
78 three centuries disclosed, step by step, the construction of many edifices which will give to  
79 the convent its heritage grandeur and appearance as we know today.

80 Thereby, it can quickly be stated different elements of the monastic complex (Fig. 2) in a  
81 chronological order: (i) Centre – Romanesque Oratory “Charola” and gothic Capitulum  
82 Room; (ii) East – Two gothic cloisters; (iii) South – Gothic Church in ruins and the gardens;  
83 (iv) North, West and South – Five renaissance styled cloisters forming with the Charola a  
84 huge Latin cross set of new dormitories; (v) North-East – Infirmary and new Pharmacy  
85 including the Knights’ Hall. Further information (not detailed in the present work) about the  
86 history and composition of the convent can be found in the following literature [17, 18, 19].

87 After the Portuguese Liberal Revolution, the Order of Christ was extinct in 1834 with the  
88 forced departure of the religious friars. From the early beginning of the 20<sup>th</sup> century, some  
89 edifices were then occupied by either the Army or the Overseas Missions Seminar. In the  
90 1980’s, the Portuguese State reacquired the whole monumental complex, designated as  
91 Convent of Christ, for cultural and touristic activities that still run nowadays. It should be  
92 noted that the Convent of Christ was classified as a national monument in 1907, and only  
93 much later in 1983, registered in the World Heritage Site List from UNESCO. With the  
94 progressive abandonment of unoccupied convent parts in the 1970s and 80s, many timber

95 structures came up with pathologies, such as leaking water in the roof covering that triggered  
1 96 the onset and development of biological wood-deteriorations over time.

3 97 In that context, three timber roof structures featuring major disorders have been investigated  
4 98 in the present work. They are respectively located in the dormitory Room 68 on the northern  
5 99 flank of the convent, and in the Knights' Hall at the north-eastern corner of the Infirmary  
6 100 complex (Fig. 2). Through applying an inspection and diagnosis methodology to those case  
7 101 studies, the resulting analysis and proposal of interventions could be extended in the near  
8 102 future to some auxiliary rooms that include similar roof structures and pathologies in the  
9 103 Convent of Christ. Concomitantly, a wood dendrochronological survey has mostly been  
10 104 carried out in the Room 68, while very recently, a further geometrical assessment of the  
11 105 ceiling structure through laser scanning and drill resistance testing has been achieved by  
12 106 Cuartero et al. [20] in the Knights' Hall.

## 23 107 **2.2. Inspection and diagnosis methodology**

25 108 Many methodological approaches for a mono- or multi-level characterization of timber  
26 109 structures *in-situ* can be found from the literature [2, 3, 4, 5, 6]. Including a variety of actions  
27 110 and solutions, different methods may be feasible if they have been chosen wisely on case by  
28 111 case basis. Regarding the assessment of timber roof structures in the Convent of Christ, a  
29 112 methodology of inspection and diagnosis (Fig. 3) has been proposed into three main steps: (i)  
30 113 Preliminary evaluation; (ii) Structural analysis and detailed diagnosis; (iii) Results and future  
31 114 interventions.

- 32 115 - The preliminary evaluation firstly consists in a desk survey, through gathering all  
33 116 handwritten and/or computer documents available (e.g. blueprints, reports, pictures...)  
34 117 dealing with the history of the building and timber structures investigated. Afterwards,  
35 118 a visual inspection takes place *in-situ* in order to report the current state of timber  
36 119 structures in their service life, and if appropriate, their pathologies (e.g. structural  
37 120 disorders, biological wood-deteriorations, serviceability defects...). A geometric  
38 121 survey is also performed *in-situ* in order to identify and measure the structural  
39 122 elements and joints. Furthermore, it helps in defining better the main construction  
40 123 and/or modification stages of the structure in the building history;
- 41 124 - The structural analysis and detailed diagnosis mainly aim at completing the  
42 125 information already collected in the first step. Before performing the structural  
43 126 analysis, the impact of the pathologies observed for the visual inspection on the wood  
44 127 mechanical properties has to be investigated. To this end, a wood diagnosis is carried

128 out *in-situ* through using non- and/or semi-destructive tests wisely selected on case by  
129 case basis. [21]. In fine, the timber structure is analysed on numerical software in  
130 order to detect the elements or joints featuring potential problems that could threaten  
131 the structural safety and integrity.

- Based on the results obtained from the last two steps, preliminary and diagnosis reports are written as the assessment of the timber structure is going. In addition to this, the third step aims at proposing a work-plan of feasible interventions, in the respect with the restoration principles stated in both charters from ICOMOS [7, 8], in order to solve current problems and prevent the onset and development of any further pathology. Thereby, the safety and integrity of timber structures will be preserved in the future through enabling maintenance actions from time to time.

### 3. Visual inspection

#### 3.1. Room 68

In the dormitory Room 68 located on the northern flank of the Convent of Christ, the roof structure and the ceiling planks (Fig. 4-a) have been selected as the first case study due their badly state of conservation in the 20<sup>th</sup> century [17, 18]. In order to ensure the visual inspection and diagnosis *in-situ*, it has been decided to remove some ceiling planks that covered the rafters and joists of the roof structure (Fig. 4-b). Also, only the northern and western parts of the structure have been investigated since they were highly subject to leaking water due to maintenance lack of roof covering, which made easier the onset and development of biological deteriorations over time on those areas.

Based on the 3D modelling of the old roof structure illustrated in Fig. 5, different timber elements can be gathered into two categories: (i) Ceiling structure; (ii) Primary roof structure. The joists and edge beams belong to the ceiling structure whereas the struts, purlins, rafters, collar ties and wall plates make up the primary structure which formerly counteracted the roof covering and outside loadings. It should be noted that all the timber elements are tied in to each other, side by side, with nails. The birdsmouth joint, which links the rafter-end with the wall plate, also includes one or two nails in order to avoid any out-of-plane displacement of the generating truss constituted by the rafter, collar tie and strut of the rafter. The remaining purlins formerly bearded into three local points the rafters subject to bending due to the action of the roof loading.

159 As shown in Fig. 6-a, two different timber structures coexist underneath the roof of the Room  
160 68. The old structure under investigation had been built in the first half of the 16<sup>th</sup> century  
161 with the dormitory rooms whereas the new one was recently settled when restoring the whole  
162 roof covering in 2007 [18]. Since the new structure bears the roof and outside loads, the old  
163 one has been restrained in its initial structural role, being now subject to its own weight and  
164 those from the ceiling planks only. Also, the top part of the rafters was cut and removed from  
165 the old structure because they were severely damaged due to biological agents. Nowadays,  
166 fungal decay at the rafter-ends and insect wood-deterioration on the external surfaces can still  
167 be observed (Fig. 6-b), resulting in a significant reduction of the timber element cross-  
168 sections. Indeed, many rafter-ends, including birdsmouth joint, and some parts of the wall  
169 plates are featured by a deterioration level so high that some of them (I, IV, V, VI and X) are  
170 nearly free of any support, leading to potential structural disorders.

171 Old and new roof structures present different wood species. As per Silva [18], Oak was  
172 identified as the main wood species for the old structure whereas the new one appeared to be  
173 made of Pine wood. Furthermore, preliminary visual investigation concluded that the rafters,  
174 joist, edge beams, collar ties, purlins and struts could be made of chestnut (*Castanea sativa*  
175 Mill.), but of Portuguese oak (*Quercus faginea* Lam.) for the wall plates. Regarding ceiling  
176 planks, maritime pine (*Pinus pinaster*) is the most likely wood species.

177 This information was confirmed in the dendrochronological study performed by the  
178 researchers from the University of Coimbra, through sampling wood carrots within the old  
179 roof structure, mostly in the rafters. As another outcome from this study, average wood  
180 density of 613 kg/m<sup>3</sup> can be assumed for all the timber elements made of *Castanea sativa*. As  
181 detailed in Table 1, this mean value is reliable when comparing with the European Standards  
182 (e.g. EN 350 [22], EN 1912 [23] and EN 338 [24]), although it seems higher than the value  
183 recommended by the Italian Standard UNI 11035-2 [25].

## 184 **3.2. Knights' Hall**

### 185 **3.2.1. Octagonal dome**

186 In the north-eastern corner of the Convent of Christ, the timber structure covering the  
187 Knight's Hall has been chosen as second case study in the present research project. The  
188 "dome" stands for a 8-face pyramidal structure whose the top is featured by a void due to the  
189 geometrical assemblage of the ceiling planks (Fig. 7-a). On the bottom part of the timber  
190 structure, decorative paintings classified as artwork under heritage protection can be observed  
191 on the ceiling planks (Fig. 7-b). The octagonal dome and the ceiling paintings had been

192 completed in the second half of 17<sup>th</sup> century [17, 18], in the same period than the convent  
193 Infirmary and Pharmacy. It should also be noted that some conservation and restoration works  
194 were performed on the structure between 1965 and 1970 [19].

195 Based on the visual inspection, each component of the octagonal dome has been modelled, as  
196 shown in Fig. 8. Thereby, it can be stated: (i) 8 pyramid-edges constituting of 3 beams each  
197 one; (ii) 6 panels of 9 joists (faces I-II-III-V-VI-VII); (iii) 2 panels of 10 joists (faces IV-  
198 VIII); (iv) 12 wall and 4 support beams making up the base of the structure. Again, the timber  
199 components are connected side by side with nails while the nailed birdsmouth joint links the  
200 ceiling joists and pyramid-edge beams to the wall and support beams. Exempt of any  
201 structural role as regard the roof covering, the octagonal dome was designed to only bear the  
202 decorative ceiling planks and the pendant light. Since the pyramidal ceiling structure in the  
203 Knights' Hall and the roof structure in the dormitory Room 68 share similar texture, colour  
204 and dating of wood, it can thus be inferred that the wood species is still chestnut (*Castanea*  
205 *sativa*). On the other hand, the decorative ceiling planks are probably made of maritime pine  
206 (*Pinus pinaster*). From the work of Cuartero et al. [20], some attempts in assessing a detailed  
207 geometry of irregular cross-section of timber elements, with non-visible faces and affected by  
208 biological wood-deterioration, have been carried out very recently, through a campaign of  
209 laser scanning and Drilling Resistance testing for the whole octagonal dome.

210 As structural disorder, the valley rafter from the northern roof under collapsing process tends  
211 to locally press the top of the octagonal dome (Fig. 9-a), in the vicinity of three pyramidal-  
212 edge beams between the faces V and VI, leading to a transfer of extra loading. On the other  
213 hand, slight and moderate insect wood-deteriorations can be noticed on the external surfaces  
214 of joists and edge beams. Furthermore, the joists (7-8-9) from the face V have been indicated  
215 as highly degraded due to the same biological agent, resulting in a significant reduction of  
216 their cross-sections (Fig. 9-b). Also, those timber elements may occasionally be wet due to the  
217 water dripping from the roof covering badly maintained. If those pathologies stated for the  
218 visual inspection still remain in the future, the structural integrity of the dome as well as the  
219 conservation of the classified paintings on the ceiling planks may be threatened in a long  
220 term, resulting in severe and irreversible consequences.

### 3.2.2. Carpentries set

221  
222 A complex timber carpentries set, standing above the octagonal dome in the Knights' Hall,  
223 has been chosen as third case study. After assessing the geometry, position and orientation of  
224 each timber components *in-situ*, the whole carpentries set has been modelled successfully



225 (Fig. 10). As a result, 50 timber elements have been identified in total and sorted out into 6  
226 groups: (i) 2 horizontal beams; (ii) 12 purlins; (iii) 4 ridges; (iv) 15 struts; (v) 2 timber trusses;  
227 (vi) 4 valley rafters. For each group, the timber components are connected side by side with  
228 nails. It should be noted that the purlins, ridges and horizontal beams are supported at their  
229 end on masonry pillars that appear to be settled and covered with lime mortar.

230 Among this myriad of timber elements, two categories of truss stand out: (i) The King-post  
231 truss (Truss A); (ii) The A-shaped truss (Truss B). The King-post truss (Fig. 11-a) is made up  
232 of two rafters (1 and 5), one collar tie (22) in tension, and one king-post (23) connected with  
233 four struts (24, 25, 26 and 27) that bear the respective valley rafters (37, 49, 43 and 30) from  
234 the roof covering. Furthermore, metallic U-shaped binding strips with bolts were used to  
235 strengthen the Single Step Joints between the rafters and collar tie, while this technique  
236 restrained any out-of-plane displacement of the king-post-end. On the other hand, the A-  
237 shaped truss (Fig. 11-b) includes two rafters (17 and 18), one collar tie (19) in compression,  
238 and two struts (20 and 21) that hold the respective purlins (45 and 47) from the roof covering.

239 Although the Knights' Hall had been built with the infirmary and pharmacy in the second half  
240 of the 17<sup>th</sup> century [17, 18], the existing carpentries set appears to belong to the 19<sup>th</sup> or 20<sup>th</sup>  
241 century. Indeed, the rendering of the timber components looks much more refined, suggesting  
242 that bench works in wood or modern manufacturing methods (e.g. sawing and machining)  
243 were used for that purpose. Even if there is no certified manuscript or report, the roof  
244 structure might have been built in 1970, during the major works standing for the repair and  
245 substitution of the whole roof in the Infirmary and Pharmacy, including the Knights' Hall  
246 [19]. With the exception of 10 struts (2, 4, 14, 15, 19, 20, 21, 28, 29 and 48) that are made of  
247 chestnut (*Castanea sativa*), eucalyptus (*Eucalyptus globulus* Labill.) is the main wood species  
248 observed for the whole carpentries set.

249 Apart from 4 timber elements (14, 15, 49, 50) superficially deteriorated due to former insect  
250 attacks, no significant biological degradation has been noticed within the whole carpentries  
251 set. On the other hand, many structural disorders can be reported: (i) Out-of-plane  
252 displacement of the king-post-end (23) within the King-post truss (Fig. 12); (ii) Slightly  
253 twisted timber elements (1, 5, 6, 11, 22, 35, 45) over their whole length (Fig. 12); (iii) Tensile  
254 crack at the mid-span of the horizontal beam (11) under excessive bending (Fig. 13-a); (iv)  
255 Collapse of the purlins (36, 38, 39, 41, 42, 44) due to the partial or complete failure of their  
256 respective masonry supports (Fig. 13-b). All these pathologies previously stated constitute the  
257 proof that the northern part of the roof has already started to collapse since a while. As

258 transient prevention mean, metallic struts were thus added accordingly, by holding on two  
259 purlins (35, 44) in the vicinity of the masonry supports.

## 260 **4. Non-destructive wood diagnosis**

261 Among different non-destructive methods proposed to establish a better diagnosis of historic  
262 timber structures [21], Ultrasonic Pulse Velocity, Drilling Resistance and Impact Penetration  
263 tests have been selected and performed *in-situ*, in respect with the observations previously  
264 made from the visual inspection. Thereby, the non-destructive wood diagnosis mostly focuses  
265 on the roof structure in the Room 68 and the octagonal dome in the Knights' Hall, since they  
266 both feature significant wood-deteriorations due to xylophagous insect and decay fungi. On  
267 the other hand, the carpentries set, reported as a sound and recent timber structure in  
268 accordance with the visual inspection, has been disregarded from this step.

### 269 **4.1. Ultrasonic Pulse Velocity test**

270 Ultrasonic Pulse Velocity (UPV) test enables to measure the propagation time, and thus, the  
271 propagation velocity of stress waves inside wood, between the transmitter and receiver probes  
272 [26, 27, 28]. Furthermore, UPV method can be considered as a quality index of wood since it  
273 can detect any superficial or internal defect (e.g. cracks, knots, biologically wood-  
274 deterioration, foreign body...). Indeed, lower velocities or longer propagation times disclose  
275 bad conditions of wood in term of physical and mechanical properties. The propagation  
276 velocity of stress waves  $v$  [m/s] essentially depends on the density  $\rho$  [kg/m<sup>3</sup>], stiffness, and  
277 thus, the elastic modulus of wood  $E$  [N/mm<sup>2</sup>], which can be estimated by the empirical  
278 equation simplified (1)[28]. According to the same authors, the elastic modulus could then be  
279 correlated with the compressive and tensile strengths of wood parallel to the grain through  
280 empirical equations, featuring low and moderate coefficients of determination though.

$$E = v^2 \cdot \rho \quad (1)$$

281 Due to heterogeneous contact conditions on external surfaces of the structural element (gaps,  
282 rough or rounded surface), it is sometimes challenging to ensure a good propagation of stress  
283 waves inside wood between both probes. For that reason, UPV testing, through using the  
284 equipment Pundit Lab<sup>®</sup> with two 54 kHz frequency transmission transducers, has only been  
285 performed for the rafters located in the Room 68. Conform with the work of Feio et al. [28],  
286 two types of UPV tests have been performed in-situ in order to estimate the wood  
287 compressive elastic moduli parallel and perpendicular to the grain: (i) Indirect Method  
288 parallel to the grain (Fig. 14-a); (ii) Direct Method perpendicular to the grain (Fig. 14-b). It

289 should be noted that both methods require having access to at least two opposite faces of the  
1 290 investigated element. In all tests, a constant pressure has been applied by means of a rubber in  
2 291 order to make easier the transmission of ultrasounds inside wood between both probes.

3 292 As a result, elastic moduli parallel and perpendicular to the grain, noted  $E_{c,0}$  and  $E_{c,90}$   
4 293 respectively, have been calculated by the equation (1), through taking into account the  
5 294 average wood density  $\rho=613 \text{ kg/m}^3$  given in Table 1 for chestnut (*Castanea sativa*). Besides,  
6 295 each part of the rafters assessed through UPV tests have been sorted out into four biological  
7 296 wood-deterioration groups (Fig. 15), in respect with both compressive elastic moduli  $E_{c,0}$  and  
8 297  $E_{c,90}$ : (i) Sound; (ii) Slightly damaged; (iii) Moderately damaged; (iv) Severely damaged.  
9 298 Lower bound values regarding the “Sound” group have been inferred from the characteristic  
10 299 and mean values of both properties  $E_{c,0}$  and  $E_{c,90}$ , in respect with the strength class D18  
11 300 assigned to the chestnut (*Castanea sativa*) in accordance with the Standard EN 338 [24]. It  
12 301 has been shown that biological wood-deteriorations, mainly due to insect attacks, are  
13 302 randomly distributed on the external surfaces of studied rafters. Nonetheless, three rafters (X,  
14 303 XI, XII) and most of the rafter-ends in the vicinity of the decayed birdsmouth should draw  
15 304 some attention, since the related external surfaces have been reported as severely damaged.  
16 305 Furthermore, low values of  $E_{c,90}$  recorded may also be explained by the presence of internal  
17 306 cracks in the element cross-section.

#### 34 307 **4.2. Drilling Resistance test**

35 308 The Drilling Resistance (DR) test consists of measuring wood drilling resistance as a function  
36 309 of penetration depth [28, 29, 30, 31]. Since the diameter of the drilled hole in the element does  
37 310 not exceed 3 mm diameter, the DR regarded as a quasi-non-destructive test has no impact on  
38 311 the wood mechanical performances, neither on the integrity of heritage structures assessed *in*  
39 312 *situ* (Fig. 16).

40 313 Information given from DR test includes: (i) The wood drilling resistance; (ii) The cross-  
41 314 section dimensions of the timber element studied; (iii) The detection and location of inner  
42 315 defects or structural discontinuities (e.g. knots, cavities, cracks, deteriorated wood...) that  
43 316 could not be noticed for the visual inspection; (iv) The annual wood growth rings; (v) A  
44 317 qualitative interpretation of wood density.

45 318 Whereas visual inspection often overestimates the amount of strength loss due to decay, DR  
46 319 testing may disclose significant drilling resistance in the reduced cross-section [30]. In that  
47 320 case, preservation of the timber element should be promoted, instead of removing it  
48 321 permanently. To this end, the Resistance Measure (RM) [28] is calculated by the equation (2),

322 which takes into account the grey area under the drilling resistance profile (Fig. 17) and the  
323 drill penetration depth noted  $h$  in the element cross-section.

$$RM = \frac{\int_0^h Area}{h} \quad (2)$$

324 From the literature [28, 29, 31], low and moderate correlations between RM, wood density  
325 and mechanical properties have been established up to now. Meanwhile, assigning the wood  
326 strength class from Standards (e.g. EN 1912 [23] and EN 338 [24]), to the elements  
327 investigated should not be based on qualitative RM values only. On the other hand, the wood  
328 moisture content should be assessed when performing DR testing, since it conditions the  
329 parameter RM as well as the wood mechanical performances.

330 Regarding the old roof structure (Room 68) and octagonal dome (Knights' Hall), DR testing  
331 has been performed for the rafters and joists, through using the Resistograph® 3450  
332 RINNTECH (Fig. 16), in the vicinity of the birdsmouth joint. After plotting the drilling  
333 resistances on graph (Fig. 17), two different parameters RM have been calculated by (2), one  
334 without defects, and the other one with defects (e.g. internal cracks and biologically  
335 deteriorated wood). For both parameters, Table 2 provides the mean values, maximum,  
336 minimum, amount of performed DR tests, standard deviation (SD) and coefficient of variation  
337 (COV). Based on very similar data distributions with  $COV < 10\%$ , it can be stated that the RM  
338 value with defects is, on average, 20% lower than the RM value without defects, resulting in a  
339 likely decrease of the wood mechanical performances as previously reported from UPV tests.  
340 As another outcome from DR testing, the thickness of the external surfaces featuring insect  
341 wood-degradations should be taken as 10 mm on average, when estimating the residual  
342 element cross-section.

### 4.3. Impact Penetration test

344 Impact Penetration (IP) test, also known as Pilodyn® Method or Dynamic Pin Penetration  
345 Method, consists of applying an impact force, through the release of a spring, by a slender  
346 steel rod on the external wooden surfaces [28, 29, 30]. Being also considered as quasi-non-  
347 destructive, IP test enables to measure the penetration depth of the rod, which is inversely  
348 proportional to density and hardness surface of wood. On the other hand, the penetration  
349 depth increases with the wood moisture content, since the latter conditions the hardness and  
350 other mechanical performances of wood. Until a maximal penetration depth of 30-40 mm, this  
351 method can be used to detect the presence of superficial defects (e.g. cracks, knots, biological  
352 wood-deterioration). Based on the penetration depth of the rod  $d_{p,rod}$  [mm] obtained from IP

tests, the related wood density  $\rho$  [g/cm<sup>3</sup>] can be estimated by the empirical equation (3) [29], with wood moisture content of 12%.

$$\rho = -0.027102 \cdot d_{p,rod} + 0.727987 \quad (3)$$

As regards the octagonal dome in the Knights' Hall, IP testing has been performed for the joists, through using the dynamic indenter Pilodyn<sup>®</sup> 6J Forest (Fig. 18), in the vicinity of the birdsmouth joint. After taking measurements of the penetration depth, the wood density has been calculated by (3), while ensuring a wood moisture content of 12% on the external wooden surfaces through using the electrical resistance moisture meter Protimeter Surveymaster<sup>®</sup>. Thereby, the mean values, maximum, minimum, amount of performed IP tests, standard deviation (SD) and coefficient of variation (COV) are given in Table 3 for three parameters: (i) Penetration depth of the rod  $d_{p,rod}$ ; (ii) Wood density  $\rho$ ; (iii) External layer thickness of deteriorated wood  $t_D$ .

The maximal density  $\rho=619$  kg/m<sup>3</sup>, that has been inferred from the minimal penetration depth  $d_{p,rod}=4$  mm, may belong to sound wood, within the range of density values detailed in Table 1 for chestnut (*Castanea sativa*). The external layer thickness of deteriorated wood  $t_D$  has then been determined through reducing the measured penetration depths  $d_{p,rod}$  by 4 mm, as a reference value standing for sound wood. As a result, the parameter  $t_D$  may vary between 0 and 11 mm, with a mean value of 5 mm. Since empirical equations from the literature [28, 29] have presented low coefficients of determination up to now, it has been decided not to estimate the wood mechanical properties based on the penetration depth.

## 5. Structural safety evaluation

After completing the preliminary inspection and non-destructive wood diagnosis, the safety evaluation of three timber structures, namely the old roof structure in the dormitory Room 68, the carpentries set and octagonal dome in the Knights' Hall, has been carried out on the Finite Element software RFEM 5.19.01 [32], by taking into account the impact of biological wood-deteriorations and other disorders noticed *in-situ* on their mechanical performances. To this end, the ultimate limit states (ULS) and serviceability limit states (SLS) have been checked for each timber roof structure, in accordance with EN 1995-1-1 (Eurocode 5) [33]. From this Standard, the coefficient of material  $\gamma_M=1.3$  and the modification factor for duration of load and moisture content  $k_{mod}=0.6$  (assumption of permanent action and service class 2) have been chosen to calculate the design values of wood strength properties, on the basis of the characteristic values provided by EN 338 [24] and UNI 11119 [34]. For each case study, the

384 minimal design bending strength  $M_{Rd}$  [kNm] has been estimated in respect with the lowest  
385 timber element cross-section. Besides, both values delimiting the range of maximal deflection  
386 permitted to still ensure a good serviceability of the structure *in-situ*, namely  $w_{L/300}=L/300$   
387 and  $w_{L/150}=L/150$  [mm], have been taken into account, for which the parameter L [mm]  
388 stands for the span of the timber element under bending on two supports.

### 389 **5.1. Roof structure – Room 68**

390 Within the old timber roof structure located in the dormitory Room 68, the numerical analysis  
391 focused on the rafters and ceiling joists in the northern and western parts suffering from a lack  
392 of maintenance over time. From the preliminary inspection and diagnosis, the element cross-  
393 sections have been determined, with the strength class D18 as mechanical properties  
394 attributed to sound chestnut (*Castanea sativa*), in accordance with EN 338 [24]. Furthermore,  
395 the roof structure belongs to the visual grade I (UNI 11119 [34]), for which three  
396 characteristic values of chestnut strength properties have been considered: (i) Compression  
397 strength parallel to the grain  $f_{c,o,k}=11$  MPa; (ii) Tensile strength parallel to the grain  $f_{t,o,k}=11$   
398 MPa; (iii) Bending strength  $f_{m,k}=12$  MPa.

399 Nonetheless, the elastic moduli have been modified in accordance, through partitioning each  
400 rafter, based on the results obtained from the Ultrasonic Pulse Velocity test. Concerning the  
401 definition of the residual element cross-section, a remaining capacity factor with a value  
402 between 0 and 0.5 could be assigned to the area attacked by a biological deteriorating agent  
403 [35]. In order to simplify the current model, it has been decided to reduce the cross-sections of  
404 the rafters and joists by an average thickness of 1 cm that stands for the external wooden layer  
405 featuring insect degradations with no remaining capacity factor, conform with the outcomes  
406 obtained from the Drilling Resistance test.

407 Because the old structure does not have to bear anymore the roof covering loadings since the  
408 restoration works performed in 2007, only two own-weights should be considered: (i) Weight  
409 of the roof structure (6.13 kN/m<sup>3</sup>) made of chestnut (*Castanea sativa*); (ii) Weight of the  
410 ceiling planks (0.2 kN/m<sup>2</sup>), made of maritime pine (*Pinus pinaster*). As illustrated in Fig. 19-a  
411 and -b, the internal forces (ULS) and local deformations (SLS) obtained after running the  
412 numerical analysis in RFEM present very low values, namely a maximal bending moment  
413 ( $M=0.07$  kNm) and maximal deflection ( $w=2$  mm) over 2000 mm span length, in comparison  
414 with the minimal bending strength ( $M_{Rd}=0.4$  kNm) and the inferior boundary value of the  
415 maximal deflection range ( $w_{L/300}=6.7$  mm). Although the whole roof structure has remained

safe so far, several decayed birdsmouth joints linking the rafter-end to the wall plate should be repaired in order to avoid any global disorder in the near future.

## 5.2. Carpentries set – Knights’ Hall

Regarding the carpentries set standing above the octagonal dome in the Knights’ Hall, severe structural disorders have been noticed, such as the tensile crack at the mid-span of the horizontal beam (11) under excessive bending and the failure support of the purlin (42) that both lead to a progressive collapse of the northern roof part. In order to figure out how these disorders came out and developed over time, two case studies have been tackled: (i) Initial design configuration of the carpentries set without any disorder; (ii) Carpentries set including one purlin (42) free of any support. Featuring no biological degradation, the element cross-sections have been defined with the strength classes D18 and D30, for the chestnut (*Castanea sativa*) and eucalyptus (*Eucalyptus globulus*) respectively, from EN 1912 [23], and EN 338 [24]. In addition to the own-weight of the carpentries set ( $6.4 \text{ kN/m}^3$ ), the permanent load related to the roof covering ( $0.8 \text{ kN/m}^2$ ) has to be taken into account, encompassing the weight of the wooden planks and ceramic tiles.

For the case study I (Fig. 20-a and -c), the maximal value of internal bending moments, located at the mid-span of the horizontal beam (11), almost exceeds 50% of the bending strength of the timber element ( $M_{Rd}=9.2 \text{ kNm}$ ), while the related deflections reach the inferior boundary value of maximal deflection range ( $w_{L/300}=19.4 \text{ mm}$ ). Although the structural safety has been checked, the initial design of the carpentries set presents a weak stiffness for both horizontal beams (11) and (6).

Regarding the case study II (Fig. 20-b and -d), higher values of internal bending moments ( $M=7.45 \text{ kNm}$ ) have been recorded, as equivalent to 80% of the bending strength of the horizontal beam (11), resulting in a tensile failure under excessive bending and lateral torsional buckling. Besides, significant deflections higher than the superior boundary value of maximal deflection range  $w_{L/150}=38.8 \text{ mm}$  have been reported. It has been concluded that the deficient anchorage of the purlin (42) in the masonry pillar has progressively failed over time, leading to the collapse of the northern roof part observed nowadays within the carpentries set.

## 5.3. Octagonal dome – Knights’ Hall

Within the octagonal dome above the Knights’ Hall, low and moderate insect wood-deteriorations have been noticed on the external surfaces for most of the joists and pyramidal-edge beams assessed. Likewise in the roof structure from the dormitory Room 68, wood

448 mechanical properties have been defined for the structural elements constituting the dome, as  
1 449 belonging to strength class D18 and visual grade I for sound chestnut (*Castanea sativa*), in  
2  
3 450 accordance with Standards EN 338 [24] and UNI 11119 [34]. Conform with the outcomes  
4  
5 451 obtained from the Drilling Resistance and Impact Penetration tests, the element cross-  
6  
7 452 sections, previously determined from the visual inspection, have been reduced by an average  
8  
9 453 thickness of 6 mm, through considering the external wooden layer degraded due to insect  
10  
11 454 attacks with no remaining capacity factor [35].

12 455 Since the octagonal dome stands for a ceiling structure, three own-weights have to be taken  
13  
14 456 into account: (i) Weight of the structural components (6.13 kN/m<sup>3</sup>) made of chestnut  
15  
16 457 (*Castanea sativa*); (ii) Weight of the decorative ceiling planks (0.2 kN/m<sup>2</sup>), made of maritime  
17  
18 458 pine (*Pinus pinaster*); (iii) Decorative iron pendant light (0.5 kN). With the collapse of the  
19  
20 459 northern roof part, the rafter valley (43) from the carpentries set tends to press the top of the  
21  
22 460 octagonal dome. In order to model this structural disorder, an extra permanent load (3.5 kN)  
23  
24 461 has been applied on the upper part of the pyramidal-edge beams between the panels V and VI.  
25  
26 462 As a result, it has been shown that the maximal value of internal bending moments (ULS), at  
27  
28 463 the location point of the extra load that simulates the consequences of the northern roof part  
29  
30 464 falling on the octagonal dome, does not exceed 50% of the minimal bending strength, namely  
31  
32 465  $M_{Rd}=3$  kNm (Fig. 21-a). The latter term has been estimated based on the lowest cross-section  
33  
34 466 among all the ceiling joists, while the extreme values of the maximal deflection range have  
35  
36 467 been calculated by considering a maximal joist length  $L=3200$  mm. On the other hand,  
37  
38 468 significant deflections (SLS) measured for three joists (III-7, V-8, VIII-3), from the panels III,  
39  
40 470 V and VIII respectively (Fig. 21-b), almost reached the superior boundary value of the  
41  
42 471 maximal deflection range  $w_{L/150}=21.3$  mm. Although the structural safety of the octagonal  
43  
44 472 dome has been checked, the singular deflections observed for those three joists should be  
45  
46 reduced in order to avoid any damage of the decorative ceiling planks in the future.

## 47 473 **6. Prevention and intervention measures**

48  
49

50 474 In this chapter, several prevention and intervention measures have been proposed for the three  
51  
52 475 timber roof structures investigated, by taking into account the outcomes from the visual  
53  
54 476 inspection, non-destructive wood diagnosis and structural analysis. As regards the latter, the  
55  
56 477 safety and integrity of structures have to be preserved and/or enhanced, by preventing the  
57  
58 478 onset and development of severe pathologies in the future. Many examples of prevention and  
59  
60 479 intervention measures to preserve long-term performances of timber structures in their service  
61  
62 480 life can be found as a non-exhaustive list from the literature review of Verbist et al. [1].



481 **6.1. Minor interventions**

1  
2 482 As first minor intervention, cleaning the roof in the dormitory Room 68 and Knights' Hall  
3  
4 483 must be performed by removing dust, mud, wooden waste or rubbles accumulated near the  
5  
6 484 masonry support, since their presence, to say nothing of the adequate range of temperature  
7  
8 485 and humidity, may trigger and speed up the long-term degradation of timber structures due to  
9  
10 486 biotic agents, such as wood-destroying insects and fungi. Also considered as a source of  
11  
12 487 future biological infestation, the external layer of joists and rafters, which has been reported  
13  
14 488 as degraded due to insect attacks for the visual inspection, has to be removed as well, through  
15  
16 489 using wood carving chisel tools for instance. Afterwards, surface and/or inner treatments  
17  
18 490 against this pest should be selected wisely and applied *in-situ* on the remaining timber  
19  
20 491 elements. Besides ensuring a proper air ventilation, monitoring the indoors exposure  
21  
22 492 conditions of timber roof structures (i.e. ambient temperature, relative humidity and wood  
23  
24 493 moisture content) should be promoted in order to faster detect wood deteriorations and stop  
25  
26 494 their development over time. In the dormitory Room 68, the totality of decayed ceiling planks  
27  
28 495 under the old roof structure should be replaced by new ones made of the same wood species  
29  
30 496 (i.e. *Pinus pinaster*), and treated in respect with the current design configuration. On the other  
31  
32 497 hand, conservation works should be hold from time to time in order to preserve the decorative  
33  
34 498 ceilings as heritage values, underneath the octagonal dome, in the Knight's Hall.  
35  
36 499 Since the repair and substitution works performed in 1970 in the Knights' Hall, the 50-years  
37  
38 500 old roof covering has been eroded over time, for lack of maintenance, leading to service  
39  
40 501 nuisances such as leaking water within the carpentries set and octagonal dome. Therefore, it is  
41  
42 502 now crucial to promote a maintenance campaign of the roof covering, which will help in  
43  
44 503 preventing leaking water in long-term, and thus, the onset and development of biological  
45  
46 504 wood-deteriorations threatening the mechanical performances of timber roof structures in  
47  
48 505 their service life. To this end, the roof covering has to be dismantled firstly, through sorting  
49  
50 506 out the well preserved ceramic tiles to reuse, from those ones damaged that have to be  
51  
52 507 substituted by new ones. Once the structural disorders present within the carpentries set will  
53  
54 508 be corrected and the timber structure returned to its initial design configuration, the  
55  
56 509 waterproofing of the roof covering should be ensured, or else enhanced. To this end, an  
57  
58 510 elastomeric waterproofing coating should be settled, underneath the ceramic tiles, on the  
59  
60 511 covering wooden planks. In addition to this, a mortar bed could be applied liberally to fill  
61  
62 512 potential gaps in-between ceramic tiles in their final implementation. Lastly, a constant  
63  
64 513 monitoring of all roofs from the Convent of Christ should be promoted in the near future to  
65  
66 514 assess their conservation state over time.

## 515 6.2. Major interventions

1  
2 516 Although the safety of the old timber roof structure has been checked in the dormitory Room  
3  
4 517 68, biological wood-deteriorations, namely fungal decay, have been noticed for many  
5  
6 518 birdsmouth joints at the rafter-end linked with the wall plate. Since those connections are  
7  
8 519 crucial in the stability of the whole structure, the rafters (I, IV, V, VI and X) featuring high  
9  
10 520 advanced stage of fungal decay at their respective end should be either strengthened or  
11  
12 521 repaired. Nonetheless, the entire removal and substitution of deteriorated timber elements  
13  
14 522 from historic roof structures by new clear ones should be excluded for conservation reasons.  
15  
16 523 Adapted from the interventions applied for the decayed timber beam-end [36], different  
17 524 techniques can be sorted out into two main categories for the birdsmouth joint (Fig. 22):

- 18  
19 525 - Retrofitting through adding new partial or full-length timber element(s) made of the  
20  
21 526 same wood species than the existing one, with or without fasteners/binding strips  
22  
23 527 connectors (e.g. steel, FRP...);
- 24 528 - Repair through settling prosthesis made of, either the same wood species than the  
25  
26 529 existing one, or another material (e.g. epoxy resin mortar, concrete...), with glued-in  
27  
28 530 plates or rods (e.g. steel, FRP...). Note that the connection of the prosthesis with the  
29  
30 531 existing element can also be external (e.g. fasteners, screwed plates...) when the  
31  
32 532 aesthetical value is not considered as an important intervention criterion.

33 533 Repair techniques are often seen as an onerous alternative that requires available passages  
34  
35 534 large enough to easily reach the intervention region, namely when cutting the decayed part  
36  
37 535 and substituting it by a prosthesis, which is sometimes very challenging to ensure within  
38  
39 536 existing timber structures. Therefore, retrofitting techniques should be preferred when  
40  
41 537 intervening in the dormitory Room 68. Regarding the octagonal dome in the Knights' Hall,  
42  
43 538 significant deflections have been reported from the structural safety evaluation for three  
44  
45 539 ceiling joists (III-7, V-8, VIII-3) under bending featuring very low cross-sections. Again, their  
46  
47 540 removal and substitution by new timber elements should be excluded for conservation  
48  
49 541 reasons. Therefore, retrofitting techniques should be considered through adding new full-  
50  
51 542 length elements, made of chestnut (*Castanea sativa*), connected alongside the existing ceiling  
52  
53 543 joist with metallic fasteners and/or binding strips in order to reduce their current deflections.  
54  
55 544 In that way, the conservation of decorative planks underneath the octagonal dome will be  
56  
57 545 guaranteed.

57 546 For the carpentries set in the Knights' Hall, the collapse of the northern roof part has been  
58  
59 547 noticed *in-situ* for the visual inspection, and afterwards confirmed from the structural analysis

548 through simulating a support failure. In that context, major intervention measures into four  
549 main steps should be promoted in order to permanently stabilize the carpentries set:

- 550 - Holding the northern part of the roof structure back in its initial design configuration  
551 through using metallic struts or even outdoors crane, bearing the respective purlins  
552 and valley rafters, during the whole intervention period. Note that the roof covering  
553 (i.e. wooden planks and ceramic tiles) should be removed beforehand;
- 554 - Strengthening the contact support between the purlins (35, 36, 38, 39, 41, 42, 44, 45)  
555 and the masonry walls with a metallic bracket anchored inside (Fig. 23). To ensure  
556 good anchorage conditions, metallic rods should be introduced inside the masonry  
557 wall, if adequate, and attached in their upper part to the bolts from the metallic  
558 bracket, which afterwards will be encased together in a concrete block;
- 559 - Substituting the damaged horizontal beam (11) by a new element made of the same  
560 wood species (*Eucalyptus globulus*), but with a higher cross-section in order to avoid  
561 any mid-span failure due to excessive bending underneath the contact area with the  
562 valley rafter. In order to enhance the compressive loads transfer, the contact surface  
563 between the horizontal beams (6, 11) and the respective valley rafters (37, 43) should  
564 be enlarged through adding some wooden wedges connected with metallic fasteners  
565 (e.g. nails, screws...) in-between both structural elements (Fig. 24);
- 566 - Removing back the metallic struts or crane that had been used to hold on the roof  
567 structure during the intervention. Lastly, putting back the roof coverings where they  
568 were before the intervention.

## 569 7. Conclusions

570 The present work has focused on the assessment of three historic timber roof structures, badly  
571 preserved over time, from the Convent of Christ in Tomar (Portugal) as a case study. From an  
572 adequate methodology of inspection and diagnosis, the roof structure in the Room 68, the  
573 octagonal dome and the carpentries set in the Knights' Hall have been assessed successfully,  
574 into four main steps: (i) Visual inspection; (ii) Non-destructive wood diagnosis; (iii)  
575 Structural safety evaluation; (iv) Prevention and intervention measures.

576 For the visual inspection, the geometric survey has been performed through identifying and  
577 measuring each structural component. As regards the pathologies noticed *in-situ*, the old roof  
578 structure in the Room 68 and the octagonal dome in the Knights' Hall feature decayed  
579 birdsmouth joints and elements superficially deteriorated due to insect attacks. On the other

580 hand, it has been reported several structural disorders within the carpentries set in the  
1 581 Knights' Hall, triggering the progressive collapse of the northern roof part over time.  
2  
3 582 Concerning the non-destructive wood diagnosis, it has been shown the efficiency of three  
4  
5 583 non-destructive tests, namely the Ultrasonic Pulse Velocity, the Drilling resistance and the  
6  
7 584 Impact Penetration tests, in the detection of wood defects within the three roof structures  
8  
9 585 assessed *in-situ*. Based on the results obtained from the Ultrasonic Pulse Velocity test, the  
10  
11 586 elastic modulus has been estimated in respect with the wood density for the external surfaces  
12  
13 587 of sound and biologically deteriorated elements. On the other hand, their residual cross-  
14  
15 588 sections have been inferred through combining the drilling resistance graph with the  
16  
17 589 penetration depth obtained from the other two non-destructive tests.  
18  
19 590 In the third step, the three timber roof structures have been successfully modelled on the  
20  
21 591 Finite Element software RFEM<sup>®</sup>, by taking into account the impact of pathologies noticed *in-*  
22  
23 592 *situ* on their mechanical performances. It has been concluded that the progressive collapse of  
24  
25 593 the northern roof part in the Knights' Hall has been triggered by a failure support followed by  
26  
27 594 a tensile crack of a beam under excessive bending, within the carpentries set. On the other  
28  
29 595 hand, the safety of other two roof structures investigated has been checked although some  
30  
31 596 decayed birdsmouth joints should draw some particular attention in the future.  
32  
33 597 Lastly, some prevention and intervention measures have been proposed, based on the  
34  
35 598 outcomes obtained from the previous steps, for the three timber roof structures investigated, in  
36  
37 599 order to preserve and enhance their safety and integrity in the future within the Convent of  
38  
39 600 Christ. Nonetheless, a strong collaboration between architects, engineers, historians and  
40  
41 601 artisans is necessary to ensure economically-viable, sustainable, and reversible if possible,  
42  
43 602 solutions in the respect with the restoration principles and present heritage values.

## 603 **Acknowledgments**

604 This work was financed by FEDER funds through the Competitively Factors Operational  
605 Programme - COMPETE and by national funds through FCT – Foundation for Science and  
606 Technology within the scope of the research project INVISIBLE WOODS PTDC/EPH-  
607 PAT/2401/2014, and the PhD Scholarships SFRH/BD/128580/2017. Besides, we would also  
608 like to acknowledge Prof. Cristina Nabais, from the University of Coimbra, for her  
609 collaboration dealing with the dendrochronological part, and last but not least, the DGPC for  
610 opening the doors to the wonderful Convent of Christ in Tomar and for the permission to  
611 investigate the timber roof structures in the dormitory Room 68 and Knights' Hall.

613 **References**

- 1  
2  
3  
4 614 [1] Verbist, M., Nunes, L., Jones, D., Branco, J.M. (2018). Chapter 11: Service life design  
5 615 of timber structures. *Long-term Performance and Durability of Masonry Structures –*  
6 616 *Degradation Mechanisms, Health Monitoring and Service Life Design – Part III: Long-*  
7 617 *term performance and service life design.* 1<sup>st</sup> Edition. Eds.: Ghiassi, B., Lourenço P.B.,  
8 618 pp 311-336. November 30, 2018. <https://doi.org/10.1016/B978-0-08-102110-1.00011-X>  
9  
10  
11 619 [2] Freas, A. (1982). Evaluation, Maintenance and Upgrading of Wood Structures – A  
12 620 Guide and Commentary. *American Society of Civil Engineers (ASCE)*, New York, USA.  
13  
14 621 [3] Teles, C.D.M., Do Valle, A. (2001). Wood structures: Acting before deterioration.  
15 622 *Historical Constructions.* Eds.: P.B. Lourenço, P. Roca, pp 857-866. Guimarães,  
16 623 Portugal, 2001.  
17  
18  
19 624 [4] Sousa, H.S., Branco, J.M., Lourenço, P.B. (2014). Da inspeção de segurança na  
20 625 reabilitação de estruturas de madeira. *Intervir em construções existentes de madeira -*  
21 626 *Livro de Atas.* Eds.: H.S. Sousa, J.M. Branco, P.B. Lourenço, pp 57-70. Guimarães,  
22 627 Portugal, June 5, 2014.  
23  
24  
25 628 [5] Cruz, H., D. Yeomans, D., E. Tsakanika, E., N. Macchioni, N., A. Jorissen, A., M.  
26 629 Touza, M. Mannucci, and P. B. Lourenço, P.B. (2015). Guidelines for on-site assessment  
27 630 of historic timber structures. *International Journal of Architectural Heritage*, Vol. 9,  
28 631 Issue 3, Pages 277–89. DOI: 10.1080/15583058.2013.774070  
29  
30  
31 632 [6] Riggio, M.; Tannert, T. (2016). Structural assessment: diagnosis, before intervention!  
32 633 *World Conference on Timber Engineering - WCTE 2016.* Eds.: J. Eberhardsteiner, W.  
33 634 Winter, A. Fadai, M. Pöll. Vienna, Austria. August 22-25, 2016. ISBN: 978-3-903039-  
34 635 00-1  
35  
36 636 [7] ICOMOS Charter (1999). Principles for the Preservation of Historic Timber Structures.  
37 637 *International Council on Monuments and Sites – ICOMOS. 12<sup>th</sup> General Assembly.*  
38 638 Mexico, October 1999.  
39  
40  
41 639 [8] ICOMOS Charter (2003). Principles for the analysis, conservation and structural  
42 640 restoration of architectural heritage. *International Council on Monuments and Sites –*  
43 641 *ICOMOS, 14<sup>th</sup> General Assembly.* Victoria Falls, Zimbabwe, 2003.  
44  
45 642 [9] Yeomans, D. (2003). *The repair of historic timber structures.* Thomas Telford Ltd,  
46 643 London.  
47  
48  
49 644 [10] Bertolini, C., Toulaitos, P., Miltiadou, N., Delinikolas, N., Crivellaro, A., Marzi, T.,  
50 645 Tsakanika, E., Pignatelli, O., Biglione, G. (2007). The Timber Roof of Hagia Paraskevi  
51 646 Basilica in Halkida, Greece: Multi-Disciplinary Methodological Approaches for the  
52 647 Understanding of the Structural Behaviour. Analysis and Diagnosis. *From Material to*  
53 648 *Structure – Mechanical Behaviour and Failures of the Timber Structures. ICOMOS*  
54 649 *IWC – XVI International Symposium.* Florence, Venice and Vicenza, Italy. November  
55 650 11-16, 2007.  
56  
57  
58 651 [11] Branco, J.M., Piazza, M., Cruz, P.J.S. (2010). Structural analysis of two King-post  
59 652 timber trusses: Non-destructive evaluation and load-carrying tests. *Construction and*  
60 653 *Building Materials*, Vol. 24, pp 371-383.  
61  
62  
63  
64  
65

- 654 [12] Croatto, G., Turrini, U. (2014). Restoration of historical timber structures – Criteria,  
1 655 innovative solutions and case studies. *Intervir em construções existentes de madeira -*  
2 656 *Livro de Atas*. Eds.: H.S. Sousa, J.M. Branco, P.B. Lourenço, pp 119-136. Guimarães,  
3 657 Portugal, June 5, 2014.
- 4 658 [13] Tampone, G., Ruggieri, N. (2016). State-of-the-art technology on conservation of  
5 659 ancient roofs with timber structure. *Journal of Cultural Heritage*, Vol. 22, pp 1019-1027.  
6 660 November-December 2016.
- 7 661 [14] Morandotti, M., Zamperini, E., Lucenti, S., Adrea D', M. (2016). Expeditious survey of  
8 662 historic timber roofs. An applied research for Palazzo San Felice in Pavia, Italy.  
9 663 *Proceedings of the World Conference on Timber Engineering - WCTE 2016*. Eds.: J.  
10 664 Eberhardsteiner, W. Winter, A. Fadai, M. Pöll. Vienna, Austria. August 22-25, 2016.
- 11 665 [15] Candelas-Gutiérrez, A., Borrallo-Jimenez, M. (2018). Methodology of Restoration of  
12 666 Historical Timber Roof Frames. Application to Traditional Spanish Structural Carpentry,  
13 667 *International Journal of Architectural Heritage*. DOI: 10.1080/15583058.2018.1506833
- 14 668 [16] Macchioni, N., Mannucci, M. (2018). The assessment of Italian trusses: survey  
15 669 methodology and typical pathologies. *International Journal of Architectural Heritage*,  
16 670 Vol. 12, Issue 4: Special Issue on “Existing Timber Structures”, pp 533-544. DOI:  
17 671 10.1080/15583058.2018.1442516
- 18 672 [17] Barbosa, A. (2009). *Habitar o Património: o Caso do Convento de Cristo*. Máthesis 18.  
19 673 177-193, 2009.
- 20 674 [18] Silva, J.R.M. da (2014). *Convent of Christ in Tomar: insight into 20<sup>th</sup> century*  
21 675 *interventions*. Master thesis in Architecture. Lusíada University, May 7, 2014, Lisbon,  
22 676 Portugal.
- 23 677 [19] Mendonça, I.; Marques, L.; Branco, R.; Matias, C. (2006). *Convento de Cristo/Mosteiro*  
24 678 *de Cristo (IPA.00004718/PT031418120002)*. SIPA (Eds.) – Sistema de Informação para  
25 679 o Património Arquitectónico. Lisbon, Portugal. Archived on September 15, 2015.
- 26 680 [20] Cuartero, J., Cabaleiro, M., Sousa, H.S., Branco, J.M. (2019). Tridimensional  
27 681 parametric model for prediction of structural safety of existing timber roofs using laser  
28 682 scanner and drilling resistance tests. *Engineering Structures*, Vol. 185, pp 58-67.  
29 683 <https://doi.org/10.1016/j.engstruct.2019.01.096>
- 30 684 [21] Jasienko, J., Nowak, T., Hamrol, K. (2013) Selected Methods of Diagnosis of Historic  
31 685 Timber Structures. Principles and Possibilities of Assessment. *Advanced Materials*  
32 686 *Research*, Vol. 778, pp 225–232, 2013. doi:10.4028/www.scientific.net/AMR.778.225
- 33 687 [22] EN 350 (2016). Durability of wood and wood-based products. Testing and classification  
34 688 of the durability to biological agents of wood and wood-based materials. *CEN,*  
35 689 *European Standardisation Institute*. Brussels, Belgium.
- 36 690 [23] EN 1912 (2012). Structural timber – Strength classes – Assignment of visual grades and  
37 691 species. *CEN, European Standardisation Institute*. Brussels, Belgium.
- 38 692 [24] EN 338 (2016). Structural timber – Strength classes. *CEN, European Standardisation*  
39 693 *Institute*. Brussels, Belgium.
- 40 694 [25] UNI 11035-2 (2003). Structural timber – visual strength grading rules and  
41 695 characteristics values for Italian structural timber population. *Ente Nazionale Italiano di*

696 *Unificazione. Italy.*

- 1  
2 697 [26] Sandoz, J.L., Benoit, Y., Demay, L. (2000). Wood testing using Acousto-ultrasonic.  
3 698 *Proceedings of the World Conference on Timber Engineering – WCTE 2000*. Whistler  
4 699 Resort, British Columbia, Canada. July 31 - August 3, 2000.
- 6 700 [27] Drdácký, M.F., Kloiber, M. (2006). Non-destructive survey of historic timber. *In-situ*  
7 701 *evaluation & non-destructive testing of historic wood and masonry structures*. Prague,  
8 702 Czech Republic, July 10-14, 2016, pp 8-23.
- 11 703 [28] Feio, A.O., Lourenço, P.B., Machado, J.S. (2007) Non-Destructive Evaluation of the  
12 704 Mechanical Behavior of Chestnut Wood in Tension and Compression Parallel to Grain.  
13 705 *International Journal of Architectural Heritage*, Vol. 1, Issue 3, pp 272-292, DOI:  
14 706 10.1080/15583050701300475
- 17 707 [29] Drdácký, M.F., Kloiber, M., Kotlíňová, M. (2006). Low invasive diagnostics of historic  
18 708 timber. *In-situ evaluation & non-destructive testing of historic wood and masonry*  
19 709 *structures*. Prague, Czech Republic, July 10-14, 2016, pp 24-41.
- 21 710 [30] Tannert, T., Anthony, R.W., Kasal, B., Kloiber, M., Piazza, M., Riggio, M., Rinn, F.,  
22 711 Widmann, R., Yamaguchi, N. (2014). In situ assessment of structural timber using semi-  
23 712 destructive techniques. *Materials and Structures*, Vol. 47, Issue 5, pp 767-785. May  
24 713 2014. DOI 10.1617/s11527-013-0094-5
- 27 714 [31] Nowak, T., Jasieńko, J., Hamrol-Bielecka, K. (2016). In situ assessment of structural  
28 715 timber using the resistance drilling method – Evaluation of usefulness. *Construction*  
29 716 *and Building Materials*, Vol. 102, Part 1, pp. 403–415. January 15, 2016. DOI:  
30 717 10.1016/j.conbuildmat.2015.11.004.
- 33 718 [32] Dlubal software GmbH®(2019). *Structural Engineering Software for Analysis and*  
34 719 *Design*. RFEM, Version 5.19.01. Germany, 2019.
- 36 720 [33] EN 1995-1-1 (2004). Eurocode 5 – Design of timber structures – Part 1.1: General –  
37 721 Common rules and rules for buildings. *CEN, European Standardisation Institute*.  
38 722 Brussels, Belgium.
- 40 723 [34] UNI 11119 (2004). Cultural heritage – Wooden artefacts – Load-bearing structures – On  
41 724 site inspections for the diagnosis of timber members. *Ente Nazionale Italiano di*  
42 725 *Unificazione. Italy.*
- 45 726 [35] Lourenço, P.B., Sousa, H.S., Brites, R.D., Neves, L.C. (2013). In situ measured cross  
46 727 section geometry of old timber structures and its influence on structural safety.  
47 728 *Materials and Structures*, Vol. 46, Issue 7, pp 1193-1208. July 2013. DOI  
48 729 10.1617/s11527-012-9964-5
- 51 730 [36] Arriaga, F., Peraza, F., Esteban, M., Bobadilla, I., Garcia, F. (2002). *Intervención en*  
52 731 *estructuras de madera*. AITIM ltd, Madrid.





Figure 1 – Aerial view of the Convent of Christ, in Tomar, Portugal.






Figure 2 – Second floor plan from the Convent of Christ in Tomar, with the location of timber roof structures under investigation (red areas).




Figure 3 – Methodological steps required for a complete inspection and diagnosis in historic timber structures (modified from [5]).



(a)



(b)

Figure 4 – Western rafters and northern joists made visible before (a) and after (b) removing the ceiling planks.




Figure 5 – 3D modelling and horizontal blueprint of the old roof structure in the dormitory

Room 68.



(a)



(b)

Figure 6 – Coexistence between old and new timber roof structures above the dormitory

Room 68 (a). Rafters featuring insect wood-deteriorations on their external surfaces, and fungal decay at their ends (birdsmouth joint) with the wall plates (b).





(a)



(b)

Figure 7 – Upper view of the octagonal dome (a). Paintings on the ceiling planks constituting the visible bottom part of the octagonal dome in the Knights’ Hall (b), from [20].




Figure 8 – 3D modelling and horizontal blueprint of the octagonal dome in the Knights' Hall.



(a)



(b)

Figure 9 – Beam of the northern roof structure pressing the top of the octagonal dome (a).

Severe insect wood-deterioration on the external surfaces of the joists from the panel V (b).








Figure 10 – 3D modelling and horizontal blueprint of the carpentries set above the octagonal dome in the Knights' Hall. King-post truss (Truss A) and A-shaped truss (Truss B).



(a)



(b)

Figure 11 – Components of the King-post truss (a) and the A-shaped truss (b).



Figure 12 – Collar tie (22) and both rafters (1, 5) slightly twisted over their whole length. Out-of-plane displacement of the king-post-end (23).




(a)




(b)

Figure 13 – Tensile crack of the horizontal beam (11) under excessive bending (a). Collapse of the purlin (42) due to the failure of the masonry support (b).



(a)



(b)

Figure 14 – Wave's propagation in respect to Indirect Method parallel to the grain (a) and the Direct Method perpendicular to the grain (b), through using the equipment Pundit lab<sup>®</sup>.






Figure 15 – Classification of external surfaces exposed to biological deteriorations, according to the wood compressive elastic modulus parallel ( $E_{c,0}$ ) and perpendicular ( $E_{c,90}$ ) to the grain, for the rafters in the Room 68.



Figure 16 – Resistograph® 3450 RINNTECH used for the Drilling Resistance tests.




Figure 17 – Drilling resistance graph in respect with the drill penetration depth, including Resistance Measure (RM) values with and without defects.





Figure 18 – Dynamic indenter Pilodyn® 6J Forest used for the Impact Penetration tests.




Figure 19 – Internal bending moments (a) and local deflections (b) within the old roof structure in Room 68.




Figure 20 – Internal bending moments (a, b) and local deflections (c, d) of the carpentries set in Knights’ Hall, for both case studies I (a, c) and II (b, d).




Figure 21 – Internal bending moments (a) and local deflections (b) of the octagonal dome in Knights' Hall.




Figure 22 – Techniques to retrofit or repair decayed birdsmouth joints (adapted from interventions on the decayed timber beam-end [36]).




Figure 23 – Strengthening of the purlin support with a bracket anchored in the masonry wall.




Figure 24 – Substitution of the failed horizontal beam and enhancement of the compressive contact area with the valley rafter.

Table 1 – Wood density  $\rho$  for the chestnut (*Castanea sativa* Mill.). European Standards VS dendrochronological sampling.

	$\rho$ [kg/m <sup>3</sup> ]
EN 350 [22]	540 - 650
EN 1912 [23] / EN 338 [24]	630
UNI 11035-2 [25]	550
Average of measured densities	613



Table 2 – Summary of the average Resistance Measure (RM) from the Drilling Resistance test performed in the Room 68 and Knights’ Hall.

	RM [Bit] – Room 68		RM [Bit] – Knights’ Hall	
	With defects	Without defects	With defects	Without defects
Average	355.6	462.6	389.2	466.2
Minimum	292.5	421.8	356.0	415.9
Maximum	417.5	525.9	415.2	544.7
Amount	33	21	9	15
SD [%]	33.2	31.2	22.3	34.3
COV [%]	9.3	6.7	5.7	7.4

Table 3 – Penetration depth of the rod  $d_{p,rod}$ , wood density  $\rho$  and external layer thickness of deteriorated wood  $t_D$ , inferred from the Impact Penetration test in the Knights' Hall.

	$d_{p,rod}$ [mm]	$\rho$ [kg/m <sup>3</sup> ]	$t_D$ [mm]
Average	9	473.9	5
Minimum	4	321.5	0
Maximum	15	619.6	11
Amount	28	28	28
SD [%]	0.3	74.0	0.3
COV [%]	29.1	15.6	51.0